

REPORT

TRUESDAIL LABORATORIES, INC.



CHEMISTS · MICROBIOLOGISTS · ENGINEERS
RESEARCH · DEVELOPMENT · TESTING
ESTABLISHED 1931

14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
(714) 730-6239 • (213) 225-1564
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company
Internal Mail Code 9-20
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Michael Binder
SAMPLE DATE: 10/04/94
PERMIT NUMBER: NPDES # CA0001414
SITE I.D. Torrance Stormdrain,
next to site #799

REPORT DATE: October 17, 1994

RECEIVED: October 04, 1994

LABORATORY NUMBER: 71104

Monthly Analysis as Requested

RESULTS

I, Units (150.1)	6.05
Temperature, °F	66

*ND = Not detected, below detection limit



Respectfully Submitted,
Truesdail Laboratories, Inc.

Thomas Herrin

Thomas Herrin, Manager
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.